

Figure 1

### 20 year Cum Failure Vs Temp




Figure 2




Figure 3A




Figure 3B






Figure 3C



318

Figure 4






Figure 6A




Figure 6B




Figure 6C




Figure 7A

700




Figure 7B

702




Figure 8




Figure 9

Oil vs Case Temp, LIM101-3019, all with 13dBm laser power with various SOA currents, 06-Oct-2




Figure 10

Bias Voltages for LIM101 Packages at Various Thermistor Temperature, 06-Oct-2002




Figure 11

